



	Banda 1	Banda 2	Banda 3	Multiplicador	Tolerancia	Coefficiente Temperatura
Negro	0	0	0	10^9		
Marrón	1	1	1	10^1	$\pm 1.00\%$	100 ppm/ $^{\circ}\text{C}$
Rojo	2	2	2	10^2	$\pm 2.00\%$	50 ppm/ $^{\circ}\text{C}$
Naranja	3	3	3	10^3		15 ppm/ $^{\circ}\text{C}$
Amarillo	4	4	4	10^4		
Verde	5	5	5	10^5	$\pm 0.50\%$	
Azul	6	6	6	10^6	$\pm 0.25\%$	10 ppm/ $^{\circ}\text{C}$
Violeta	7	7	7	10^7	$\pm 0.10\%$	5 ppm/ $^{\circ}\text{C}$
Gris	8	8	8	10^8	$\pm 0.05\%$	
Blanco	9	9	9	10^9		
Dorado				10^{-1}	$\pm 5.00\%$	
Plateado				10^{-2}	$\pm 10.00\%$	